



ISO 9001:2015 Certified

## **PRESS STATEMENT**

**Tuesday, 22<sup>nd</sup> March 2022:**

On the evening of Saturday 19th March 2022 at around 1900 Hours, a fully occupied six-storey building on Plot LR No. 10090/49 in Juja Town, Kiambu County was reported to be showing signs of structural failure.

The National Construction Authority, the National Disaster Management Unit, the County Government of Kiambu and other members of the multi-agency team through a collaborative effort moved with speed, evacuated all occupants to safety and secured the building. In order to safeguard the safety of the public and the surrounding property, it was deemed necessary to demolish the affected building. The building has been safely demolished and investigations to establish the cause of the structural failure have commenced. A full report will be issued once comprehensive investigations are concluded.

The Authority appreciates the quick response and collaboration from multiagency team and remains committed to ensure a well-coordinated and prosperous construction industry.

A handwritten signature in blue ink, appearing to read 'M. Akech', with a long horizontal flourish extending to the right.

**Eng. Maurice Akech, MBS**

**EXECUTIVE DIRECTOR/REGISTRAR OF CONTRACTORS**

---

*The National Construction Authority is a State Corporation established by the National Construction Authority Act No. 41 of 2011 with a mandate to oversee the construction industry and coordinate its development*

---